



## Riverbend Riverbank Water District

461 SW Hebb Park Rd, West Linn OR, 97068-9403

P.O. Box 1155, Hillsboro OR, 97123-1155



### 2025 RRWD Well Pump A Replacement – Tuesday, July 29, 2025

10:12 am – New well pump being installed now (fig.1, fig.2)

10:51 am – Well casing is not good, going to replace it all (fig.3)

11:50 am – Because the water level is lower and pump is deeper than published the pump they brought is not big enough so they have to get bigger pump.  
Can't finish today

### Wednesday, July 30, 2025

Old pump is out and new one is in but not pumping to the level we need

Two possible reasons – Either parts of the broken back flow device got into the pipes and are restricting flow or the new pump is not working correctly. Fisher is coming out again tomorrow afternoon to figure out what is up.

Fisher did a flow test then pulled the new pump and decided they had made a mistake in the size we needed. Yes it will add to the cost. They took the pump and are going to upgrade it and reinstall when the upgrade is done. Possibly Friday or at the latest Monday. Well 2 is running and keeping up with demand

fig.1



fig.2



fig.3

